



"Wallin, Sharon"  
<WallinSL@cdm.com>  
08/17/2004 03:25 PM

To "TomPerina (tperina@ch2m.com)" <tperina@ch2m.com>,  
Christopher Lichens/R9/USEPA/US@EPA  
cc "Chuck McLaughlin" <cmclaugh@demaximis.com>,  
"Chamberlin, David" <ChamberlinDC@cdm.com>  
bcc

Subject Status of OW9 Drilling

The drilling subcontractor is experiencing difficulty breaking apart the drill pipe and bit. It looks like installation of the conductor casing may be delayed until tomorrow. I will keep you posted if there is any change.

Sharon